



CPSC, The Toro Company Announce Recall of Liquid Cooled Z Master ZRT Mowers

In cooperation with the U.S. Consumer Product Safety Commission (CPSC), The Toro Company, Bloomington, Minn., is voluntarily recalling certain model Toro Z Master Z580, Z580-D, Z593-D and Z595-D liquid cooled zero turn mowers. These units were manufactured and sold from 2006-2009 and are equipped with fuel injected Kawasaki liquid cooled gasoline or Kubota liquid cooled diesel engines.

Model Numbers	Serial Numbers
74264	260000001-260999999
74265	260000001-260999999
74266	270000001-290999999
74267	270000001-290999999
74274	270000001-290999999
74253	270000001-290999999
74254	270000001-290999999

The model and serial number are located on a decal on a metal plate the right hand side of the unit just to the rear of the height of cut adjustment lever.

Problem:

The coolant system overflow bottle on these products can become over-pressurized in the event of severe engine overheating. This can result in release of the cap and a spray of hot coolant on the operator. We have had six reports of operators who received burns from this release.

What to do:

If you have an affected unit, stop using the mower and contact Toro at 866-946-3109 (U.S. & Canada) to have a free modification kit sent directly to you. Most people should be able to install this kit on their own. If you are not able to effect this modification yourself, you may contact any Toro Dealer to have it installed for you at no charge.



Side View of Mower. Seat flipped up.

