



## Toro® recalls equipment with Kohler Engines

### Affected product

Kohler engines used in Toro and Exmark mowers and compact utility loaders

### Product description

This recall involves various Toro and Exmark mowers and compact utility loaders. The Toro ZRT mowers are red and black. The Toro Dingo compact utility loaders are red and black with the exception of model 22321G which is green. The Exmark Lazer ZRT and Pioneer Series mowers are red and gray and the Exmark Navigator mower is red and gray with a white hopper.

The model and serial numbers are found in the following locations:

- For the Toro ZRT and Exmark ZRT riding mowers, on a metal plate on the front of the mower below the seat.
- For the Toro Dingo compact utility loaders, on a metal plate on the front right.
- For the Exmark Navigator riding mowers, on a metal plate below the hopper on the right hand side.

The following Toro and Exmark models and serial number ranges were sold in Canada and are equipped with the identified Kohler engine models CH740 and CV740:

Toro Brand Recalled Products		
Model Number	Serial Number Range	Description
74915	290000101 through 313000776	Toro 5000 Series Z Master
74916	312000101 through 313000227	Toro 5000 Series Z Master
22321	290000101 through 313000200	Toro Dingo TX 427 Narrow Track
22322	290000101 through 313000200	Toro Dingo TX 427 Wide Track

Exmark Brand Recalled Products		
Model Number	Serial Number Range	Description
LZA27KC604	863426 through 898201	Exmark Lazer Z Advantage Series
LZAS27KC524	793094 through 897026	Exmark Lazer Z Advantage Series

LZAS27KC604	791555 through 897538	Exmark Lazer Z Advantage Series
LZE27KC604	921923 through 980310	Exmark Lazer Z E-Series
LZE740KC604	312600125 through 313663278	Exmark Lazer Z E-Series
LZS27KC524	921598 through 975695	Exmark Lazer Z S-Series
LZS27KC604	920112 through 980915	Exmark Lazer Z S-Series
LZS740KC604	312600217 through 313641889	Exmark Lazer Z S-Series
LZX27KC526	921823 through 981002	Exmark Lazer Z X-Series
LZX27KC606	923098 through 978414	Exmark Lazer Z X-Series
LZX740KC526	312602676 through 312646532	Exmark Lazer Z X-Series
LZX740KC606	312600721 through 312653486	Exmark Lazer Z X-Series
LZZ27KC526	790624 through 896949	Exmark Lazer Z
LZZ27KC606	790100 through 897610	Exmark Lazer Z
NV27KC	933690 through 971876	Exmark Navigator
NV740KC	312603656 through 312654022	Exmark Navigator
PNS740KC604	312600117 through 313664863	Exmark Pioneer S-Series

## Hazard identified

The Kohler engine electrical system can fail and may cause a fire hazard.

The firms have received reports of 28 incidents with the recalled mowers and compact utility loaders. None of the incidents originated in Canada.

Health Canada has not received any reports of consumer incidents or injuries to Canadians related to the use of these recalled mowers and compact utility loaders.

## Number sold

Approximately 343 recalled units were sold in Canada.

## Time period sold

The recalled units were sold from 2009 to 2013 at authorized Toro and Exmark dealers across Canada.

## Place of origin

Manufactured in the United States of America.

## Companies

### Manufacturer

Recalled engines were manufactured by:	Kohler Engines N7650 CTH LS Kohler, WI 53044
Whole good units utilizing recalled engines:	The Toro Company 8111 Lyndale Avenue South Bloomington, MN 55420  Exmark Manufacturing Company, Inc. 2101 Ashland Avenue Beatrice, NE 68310

## What you should do

**Consumers should stop using the recalled products immediately and contact a Toro or Exmark dealer to have them replace the identified electrical components.**

For more information, consumers may contact Toro toll-free at 1-855-340-7689 or Exmark toll-free at 1-800-667-5296, from 8 a.m. to 5 p.m. CT Monday through Friday or visit the Toro website ([www.toro.com](http://www.toro.com)) and click on Product Recall Information on the bottom right-hand side of the page.

Please note that the *Canada Consumer Product Safety Act* prohibits recalled products from being redistributed, sold or even given away in Canada.

Health Canada would like to remind Canadians to report any health or safety incidents related to the use of this product or any other consumer product or cosmetic by filling out the Consumer Product Incident Report Form (<http://www.hc-sc.gc.ca/cps-spc/advisories-avis/incident/index-eng.php>).

## Images



Image 1 – Toro ZRT



Image 2 – Toro Dingo



Image 3 – Exmark ZRT



Image 4 – Exmark Navigator



Image 5 – Exmark Pioneer